

Installation Instructions

Mini GAC® 2500 PCT


(PRODUCT CALIBRATION TRANSFER PC TOOL)

DICKEY-john's PC Application Software tool provides a convenient method to load grain calibrations into the mini GAC® 2500 unit via a computer.

IMPORTANT: Grain calibration values vary based on region. Regions outside of North America should obtain calibrations from a local distributor.

The mini GAC® 2500 application software is compatible with Windows® operating systems 7 and 10. A downloading error will occur if the software is attempted to download on a system other than the ones listed.

Figure 1 Downloading Requirements



PC SOFTWARE INSTALLATION

To Install:

1. At the www.dickey-john.com home page, navigate to the mini GAC® 2500 PC Application software by clicking on the following path:
 - Products
 - Analytical
 - Moisture Testing
 - mini GAC® 2500
 - Get Support
 - Click 'Product Calibration Transfer Tool' to start download process
2. After download is complete, double click Disk1 to find the set up tool.
 - Double click the 'miniGAC2500_PCT_Setup' application
 - Depending on the browser, a pop-up screen will appear asking to extract all the files, continue to extract all
 - Disk1 will appear again, double click to open the file
 - Double click the 'miniGAC2500_PCT_Setup' to start the installation wizard

Installation Instructions

APPLICATION INSTALLATION WIZARD

3. Follow the wizard instructions to complete the software download.
4. If you choose "Run", the software file destination defaults to *C:\Program Files (x86)\DICKY-john\miniGAC2500_PCT* unless redirected to another file location during setup.

Figure 2 Application Wizard Main Screen



Desktop Icon



5. After a successful installation:
 - From the Start/Programs menu, click the **miniGAC2500_PCT** Icon to start the PC application tool.